

NATIONAL TRANSPORTATION SAFETY BOARD
Vehicle Recorder Division
Washington, DC 20594

May 4, 2020

Errata - Security Video Factual Report

Specialist's Factual Report
By Sean Payne

1. EVENT

Location: Miami, Florida
Date: March 15, 2018
NTSB Number: HWY18MH009

2. ERRATA

This document addresses timing and caption corrections to the following device to evidence and figures in the report from the following device:

Recorder Manufacturer/Model: GoPro
Owner: HERC Rental
Location: Truck - Eastbound - SW 8th Street
Field of View: Facing East

Correction 1. The description for frame 20, figure 4 should be changed from:

Figure 20 - Figure 4 - Debris consistent with concrete dust blowout on the north side of the bridge appears larger. Workers were visible on the canopy of the main-span in the vicinity of node 10/11.

To:

Frame 20 - Figure 4 - Debris consistent with concrete dust blowout on the north side of the bridge appears larger. Workers were visible on the canopy of the main-span in the vicinity of node 10/11.

The word *frame* was substituted for the word *figure*.

Correction 2. The timing information for the GoPro recording was calculated incorrectly. The timing information that appears in the original report was

calculated based on a frame rate of 30 frames per second. The actual frame rate of the GoPro was calculated to be 5 frames per second. The following figures should contain timing information as follows:

Frame 18 - 13:46:42.947

Frame 19 - 13:46:43.147

Frame 20 - 13:46:43.347

Frame 21 - 13:46:43.547

Frame 22 - 13:46:43.747

Frame 23 - 13:46:43.947 - Unchanged

Frame 24 - 13:46:44.147

Frame 25 - 13:46:44.347

Frame 26 - 13:46:44.547

Frame 27 - 13:46:44.747

Frame 28 - 13:46:44.947

Frame 29 - 13:46:45.147

Frame 30 - 13:46:45.347

Frame 31 - 13:46:45.547

Frame 32 - 13:46:45.747

Frame 33 - 13:46:45.947

Frame 43 - 13:46:47.947