



Aviation Investigation Factual Report

Location: RIVERSIDE, California

Date & Time: October 31, 1984, 15:30 Local

Aircraft: CESSNA 195

Defining Event:

Flight Conducted Under: Part 91: General aviation - Personal

Accident Number: LAX85FUG01

Registration: N3879V

Aircraft Damage: Substantial

Injuries: 1 None

Factual Information

Pilot Information

Certificate:	Commercial	Age:	67,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 14, 1984
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	6400 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N3879V
Model/Series:	195 195	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7347
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	JACOBS
ELT:	Installed, not activated	Engine Model/Series:	R-755-A2
Registered Owner:	GRAND CANYON DORIES INC.	Rated Power:	300 Horsepower
Operator:	CLYDE LITTON	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 LAX85FUG01

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	RIVERSIDE (RAL)	Type of Flight Plan Filed:	None
Destination:	RUBIDOUX (RIV)	Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	FLA-BOB RIR	Runway Surface Type:	Asphalt
Airport Elevation:	764 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	3200 ft / 60 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 3 of 4 LAX85FUG01

Administrative Information

Investigator In Charge (IIC): Colvin, D

Additional Participating

Persons:

Report Date: February 6, 1995

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=24541

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 LAX85FUG01