



# **Aviation Investigation Factual Report**

Location: BRAWLEY, California Accident Number: LAX92LA270

Date & Time: June 28, 1992, 19:30 Local Registration: N1794W

Aircraft: BEECH A36 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation

### **Factual Information**

#### **Pilot Information**

Certificate:	Private	Age:	61,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	June 5, 1992
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	3598 hours (Total, all aircraft), 986 hours (Total, this make and model), 3598 hours (Pilot In Command, all aircraft), 9 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 2 of 5 LAX92LA270

#### **Aircraft and Owner/Operator Information**

Aircraft Make:	BEECH	Registration:	N1794W
Model/Series:	A36 A36	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	E380
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	February 4, 1992 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	9 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1871 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-BA2
Registered Owner:	CLYDE SHIELDS ENTOMOLOGICAL SV	Rated Power:	300 Horsepower
Operator:	CLYDE E. SHIELDS	Operating Certificate(s) Held:	None
Operator Does Business As:	CLYDE SHIELDS ENTOMOLOGICAL SV	Operator Designator Code:	

#### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)		Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear		Visibility	30 miles
Lowest Ceiling:	None		Visibility (RVR):	
Wind Speed/Gusts:	15 knots /		Turbulence Type Forecast/Actual:	/
Wind Direction:	270°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:			Temperature/Dew Point:	38°C
Precipitation and Obscuration:	No Obscurati	on; No Precipita	ition	
Departure Point:	SAN DIEGO	(MYF)	Type of Flight Plan Filed:	None
Destination:			Type of Clearance:	None
Departure Time:	18:45 Local		Type of Airspace:	Class G

Page 3 of 5 LAX92LA270

## **Airport Information**

Airport:		Runway Surface Type:	
Airport Elevation:		<b>Runway Surface Condition:</b>	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

#### Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.019229,-115.450065(est)

Page 4 of 5 LAX92LA270

#### **Administrative Information**

Investigator In Charge (IIC): Rich, Jeff Additional Participating JOHN HYNDMAN; SAN DIEGO , CA NICK WEBER; SAN DIEGO , CA Persons: **Report Date:** January 16, 1997 **Last Revision Date: Investigation Class:** Class Note: **Investigation Docket:** https://data.ntsb.gov/Docket?ProjectID=27667

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX92LA270