



Registration:

Aircraft Damage:

NYC86LA208

N6637E

None

# **Aviation Investigation Factual Report**

Location: HARTFORD, Connecticut Accident Number:

**Date & Time:** August 2, 1986, 14:00 Local

Aircraft: BEECH C24R

**Defining Event:** 1 Serious, 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

### **Factual Information**

### **Pilot Information**

Certificate:	Private	Age:	31,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	April 12, 1985
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1671 hours (Total, all aircraft), 123 hours (Total, this make and model), 1456 hours (Pilot In Command, all aircraft), 195 hours (Last 90 days, all aircraft)		

### Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N6637E
Model/Series:	C24R C24R	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	MC 692
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2750 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1950 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	I0360A1B6
Registered Owner:	CENTERLINE AVIATION, INC	Rated Power:	200 Horsepower
Operator:	CENTERLINE AVIATION	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 NYC86LA208

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Scattered / 10000 ft AGL	Visibility	5 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	27 inches Hg	Temperature/Dew Point:	29°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	HARTFORD (HFD)	Type of Flight Plan Filed:	None
Destination:	NANTUCKET (ACK)	Type of Clearance:	None
Departure Time:	14:00 Local	Type of Airspace:	Class E

### **Airport Information**

Airport:	HARTFORD HFD	Runway Surface Type:	Asphalt
Airport Elevation:	19 ft msl	Runway Surface Condition:	Dry
Runway Used:	20	IFR Approach:	
Runway Length/Width:	4418 ft / 150 ft	VFR Approach/Landing:	Full stop;Precautionary landing;Traffic pattern

### Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	None
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 Minor	Latitude, Longitude:	

Page 3 of 4 NYC86LA208

#### **Administrative Information**

Investigator In Charge (IIC):	Hancock, Robert
Additional Participating Persons:	
Report Date:	February 6, 1995
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=30404

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 NYC86LA208