

Aviation Investigation Factual Report

Location:	Bakersfield, California	Accident Number:	WPR09CA143
Date & Time:	March 6, 2009, 13:45 Local	Registration:	N4134B
Aircraft:	Bellanca 17-31ATC	Aircraft Damage:	Substantial
Defining Event:	Loss of control on ground	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Pilot Information

Certificate:	Private	Age:	73,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	June 13, 2008
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 30, 2005
Flight Time:	362 hours (Total, all aircraft), 294 hours (Total, this make and model), 308 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Bellanca	Registration:	N4134B
Model/Series:	17-31ATC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	74-31102
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	November 21, 2008 Annual	Certified Max Gross Wt.:	3325 lbs
Time Since Last Inspection:	4 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3908 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	IO-540-K1E5
Registered Owner:	David N Crowe	Rated Power:	300 Horsepower
Operator:	David N Crowe	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KBFL,507 ft msl	Distance from Accident Site:	
Observation Time:	13:54 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	16°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Pauma Valley, CA	Type of Flight Plan Filed:	None
Destination:	Bakersfield, CA (BFL)	Type of Clearance:	VFR flight following
Departure Time:	12:00 Local	Type of Airspace:	

Airport Information

Airport:	Bakersfield Meadows BFL	Runway Surface Type:	Asphalt
Airport Elevation:		Runway Surface Condition:	Dry
Runway Used:	30R	IFR Approach:	None
Runway Length/Width:	10857 ft / 150 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	35.433612,-119.056945(est)

Administrative Information

Investigator In Charge (IIC):	Plagens, Howard
Additional Participating Persons:	Jim Henry; Federal Aviation Administration FSDO; Fresno, CA
Report Date:	April 6, 2009
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=73447

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.