

# **Aviation Investigation Final Report**

Location:	CLARENCE, New Yor	k	Accident Number:	BF092LA040
Date & Time:	March 14, 1992, 14:0	0 Local	<b>Registration:</b>	N7019
Aircraft:	CESSNA	180C	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal			

### **Analysis**

THE PILOT REPORTED THAT AFTER TAKEOFF, HE PUMPED THE SKIS DOWN. HE NOTICED THE SKI TIPS WERE LOW. HE STATED THAT HE DECIDED TO DO A TOUCH AND GO LANDING. DURING THE LANDING, THE RIGHT SKI DUG INTO THE SNOW AND DIRT, CAUSING THE RIGHT GEAR TO COLLAPSE. ACCORDING TO THE PILOT, THE AIRPLANE SKIDDED ABOUT 200 FEET AND NOSED OVER.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S INADEQUATE INFLIGHT DECISION TO LAND WITH A DEFECTIVE SKI LANDING GEAR ON UNSUITABLE TERRAIN, WHICH RESULTED IN A NOSE OVER.

**Findings** 

Occurrence #1: NOSE OVER Phase of Operation: LANDING

Findings

- 1. (F) LANDING GEAR, SKI ASSEMBLY INADEQUATE
- 2. (C) IN-FLIGHT PLANNING/DECISION INADEQUATE PILOT IN COMMAND
- 3. (F) OPERATION WITH KNOWN DEFICIENCIES IN EQUIPMENT PILOT IN COMMAND
- 4. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION SNOW COVERED
- 5. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA SELECTED PILOT IN COMMAND

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	64,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	November 17, 1990
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	2732 hours (Total, all aircraft), 600 hours (Total, this make and model), 2732 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft)		

#### Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N7019
Model/Series:	180C 180C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	50881
Landing Gear Type:	Ski	Seats:	4
Date/Type of Last Inspection:	June 18, 1991 Annual	Certified Max Gross Wt.:	2650 lbs
Time Since Last Inspection:	54 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	0-470-L16
Registered Owner:	MAXWELL BENNETT ASSOC.	Rated Power:	230 Horsepower
Operator:	MAXWELL BENNETT ASSOC.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

#### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	BUF ,99999 ft msl	Distance from Accident Site:	999 Nautical Miles
Observation Time:	14:00 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Unknown / 3300 ft AGL	Visibility	20 miles
Lowest Ceiling:	Broken / 3300 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	260°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-4°C / -11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	LOCKPORT , NY (0G0 )	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:30 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	POTOCZAK D57	Runway Surface Type:	Grass/turf
Airport Elevation:	587 ft msl	Runway Surface Condition:	Snow
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	2100 ft / 75 ft	VFR Approach/Landing:	Touch and go

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.980289,-78.599861(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Jones, Dennis		
Additional Participating Persons:	JAMES YOUNG; ROCHESTER , NY		
Original Publish Date:	September 28, 1993		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=11771		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.