



# **Aviation Investigation Final Report**

Location: OCONOMOWOC, Wisconsin Accident Number: CHI85LA290

Date & Time: July 15, 1985, 19:30 Local Registration: N8877F

Aircraft: HUGHES 269A Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 137: Agricultural

### **Analysis**

THE HELICPOTER CONTACTED A CORN CROP AND CAME TO REST INVERTED DURING AN AERIAL APPLICATION FLT. THE PLT STATED, 3 PASSES WERE MADE OVER THE FLD BEING SPRAYED AND AFTER A TURN TO BEGIN THE 4TH PASS, THE HELICOPTER SETTLED WITH PWR CONTACTING THE CROP.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING - AERIAL APPLICATION

#### **Findings**

1. (C) COLLECTIVE - EXCESSIVE - PILOT IN COMMAND

2. (F) JUDGMENT - POOR - PILOT IN COMMAND

3. (F) PERFORMANCE DATA - NOT UNDERSTOOD - PILOT IN COMMAND

-----

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 6 CHI85LA290

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial; Private	Age:	42,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	March 12, 1985
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	604 hours (Total, all aircraft), 300 hours (Total, this make and model), 439 hours (Pilot In Command, all aircraft), 115 hours (Last 90 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CHI85LA290

## **Aircraft and Owner/Operator Information**

Aircraft Make:	HUGHES	Registration:	N8877F
Model/Series:	269A 269A	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	73-0254
Landing Gear Type:	Skid	Seats:	2
Date/Type of Last Inspection:	June 12, 1985 100 hour	Certified Max Gross Wt.:	1550 lbs
Time Since Last Inspection:	75 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2700 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	HIO-360-A1A
Registered Owner:	HAROLDS HELICOPTER SERVICE	Rated Power:	180 Horsepower
Operator:	HAROLD MILLER	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MKE ,723 ft msl	Distance from Accident Site:	42 Nautical Miles
Observation Time:	18:50 Local	Direction from Accident Site:	30°
<b>Lowest Cloud Condition:</b>	Scattered	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	12 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	26°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	OCONOMOWC , WI	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	19:00 Local	Type of Airspace:	Class G

Page 4 of 6 CHI85LA290

## **Airport Information**

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	None

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	43.060653,-88.390426(est)

Page 5 of 6 CHI85LA290

#### **Administrative Information**

Investigator In Charge (IIC): Siegman, James

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=13143

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CHI85LA290