



Aviation Investigation Final Report

Location:	HIBBING, Minnesota	Accident Number:	CHI86LA059
Date & Time:	December 30, 1985, 10:40 Local	Registration:	N180HS
Aircraft:	CESSNA 180J	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

THE PLT LANDING IN A DIRECT 90 DEG X-WIND, LOST DIRECTIONAL CONTROL, STRUCK A SNOWBANK AND NOSED OVER INVERTED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: LANDING - ROLL

Findings

1. WEATHER CONDITION - CROSSWIND
2. (C) COMPENSATION FOR WIND CONDITIONS - POOR - PILOT IN COMMAND
3. (C) WIND INFORMATION - NOT OBTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - ROLL

Occurrence #3: NOSE OVER
Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Private	Age:	32, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	September 3, 1985
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	458 hours (Total, all aircraft), 105 hours (Total, this make and model), 428 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N180HS
Model/Series:	180J 180J	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18052597
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	June 29, 1985 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:	60 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3001 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-470U
Registered Owner:	SCOTTY'S, INC.	Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	HIB ,1352 ft msl	Distance from Accident Site:	
Observation Time:	10:35 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 1000 ft AGL	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	-15°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	DULUTH , MN (DLH)	Type of Flight Plan Filed:	None
Destination:	HIBBING , MN (HIB)	Type of Clearance:	None
Departure Time:	11:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	CHILSOLM-HIBBING HIB	Runway Surface Type:	Asphalt
Airport Elevation:	1352 ft msl	Runway Surface Condition:	Snow
Runway Used:	31	IFR Approach:	None
Runway Length/Width:	6500 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	47.540634,-92.859542(est)

Administrative Information

Investigator In Charge (IIC): Mcavoy, Edward

Additional Participating Persons: J. H THIEM; MINNEAPOLIS , MN

Original Publish Date:

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=13401>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).