



# **Aviation Investigation Final Report**

Location: FOND DU LAC, Wisconsin Accident Number: CHI88LA051

Date & Time: January 24, 1988, 15:00 Local Registration: N75716

Aircraft: CESSNA 172N Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

-----

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

-----

Occurrence #3: NOSE OVER

Phase of Operation: LANDING - ROLL

# **Factual Information**

#### **Pilot Information**

Certificate:	Student	Age:	49,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	February 5, 1987
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	56 hours (Total, all aircraft), 56 hours (Total, this make and model), 22 hours (Pilot In Command, all aircraft), 6 hours (Last 90 days, all aircraft)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	CESSNA	Registration:	N75716
Model/Series:	172N 172N	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	67897
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	January 23, 1988 100 hour	Certified Max Gross Wt.:	2220 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2501 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	0-320-H2AD
Registered Owner:	FOND DU LAC SKYPORT	Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 CHI88LA051

## **Meteorological Information and Flight Plan**

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	240°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-7°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:45 Local	Type of Airspace:	Class D

## **Airport Information**

Airport:	SKYPORT FLD	Runway Surface Type:	Asphalt
Airport Elevation:	809 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	3600 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 3 of 4 CHI88LA051

#### **Administrative Information**

Investigator In Charge (IIC): Dinwiddie, Carl

Additional Participating Persons:

Original Publish Date: September 25, 1989

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=14035

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 CHI88LA051