



Aviation Investigation Final Report

Location: NOBLESVILLE, Indiana Accident Number: CHI88LA197

Date & Time: August 6, 1988, 16:30 Local Registration: N98980

Aircraft: CESSNA 310RII Aircraft Damage: Substantial

Defining Event: 4 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING THE LANDING ROLL, SHORTLY AFTER TOUCHDOWN AND BRAKE APPLICATION, THE LEFT MAIN LANDING GEAR COLLAPSED DUE TO THE FAILURE OF THE DRAG BRACE. THE PILOT WAS UNABLE TO MAINTAIN DIRECTIONAL CONTROL OF THE AIRCRAFT AND IT VEERED OFF THE LEFT SIDE OF THE RUNWAY BEFORE COMING TO A STOP IN THE GRASS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR, NORMAL RETRACTION/EXTENSION ASSEMBLY - FAILURE, TOTAL

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

2. DIRECTIONAL CONTROL - NOT POSSIBLE

Page 2 of 6 CHI88LA197

Factual Information

Pilot Information

Certificate:	Commercial	Age:	40,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 5, 1988
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1626 hours (Total, all aircraft), 121 hours (Total, this make and model), 1502 hours (Pilot In Command, all aircraft), 46 hours (Last 90 days, all aircraft), 18 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 CHI88LA197

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N98980
Model/Series:	310RII 310RII	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	310R0675
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	July 13, 1988 Annual	Certified Max Gross Wt.:	5500 lbs
Time Since Last Inspection:	17 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	1124 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-M
Registered Owner:	ONE VJ, INC	Rated Power:	285 Horsepower
Operator:	ONE VJ, INC.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	IND ,797 ft msl	Distance from Accident Site:	7 Nautical Miles
Observation Time:	16:50 Local	Direction from Accident Site:	180°
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	30°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	29°C / 15°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	NOBLESVILLE , IN (418)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:45 Local	Type of Airspace:	Class G

Page 4 of 6 CHI88LA197

Airport Information

Airport:	INDIANAPOLIS METROPOLITAN 418	Runway Surface Type:	Asphalt
Airport Elevation:	803 ft msl	Runway Surface Condition:	Dry
Runway Used:	32	IFR Approach:	None
Runway Length/Width:	3000 ft / 75 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	

Page 5 of 6 CHI88LA197

Administrative Information

Investigator In Charge (IIC):	Reeves, Jodi	
Additional Participating Persons:	G TEMPLE; INDIANAPOLIS , IN	
Original Publish Date:	January 24, 1990	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=14137	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 CHI88LA197