

Aviation Investigation Final Report

Location:	DUBUQUE, Iowa		Accident Number:	CHI92LA193
Date & Time:	June 27, 1992, 08:	00 Local	Registration:	N73952
Aircraft:	BELL	47-2A-1	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General av	viation		

Analysis

THE PILOT WAS ATTEMPTING TO FLY THE HELICOPTER OFF OF A FLAT BED TRAILER WHEN THE ACCIDENT OCCURRED. HE STATED THAT THE RIGHT REAR SKID FELT HEAVY DURING THE LIFT-OFF SO HE APPLIED LEFT CYCLIC. WHEN AIRBORNE, HE APPLIED LEFT PEDAL AND THE HELICOPTER TURNED TO THE LEFT STRIKING A PARKED PICK-UP TRUCK.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN BOTH DIRECTIONAL CONTROL OF THE HELICOPTER AND CLEARANCE FROM THE TRUCK.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. OBJECT - VEHICLE

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Commercial: Driveta	A.m.o.	49 Mala
Certificate:	Commercial; Private	Age:	48,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical–w/ waivers/lim	Last FAA Medical Exam:	May 20, 1992
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	3400 hours (Total, all aircraft), 1117 hours (Total, this make and model), 3290 hours (Pilot In Command, all aircraft), 66 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELL	Registration:	N73952
Model/Series:	47-2A-1 47-2A-1	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2865
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	April 10, 1992 Annual	Certified Max Gross Wt.:	2850 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	9648 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	VO-435-A1F
Registered Owner:	BADGER HELICOPTERS, INC.	Rated Power:	265 Horsepower
Operator:	BADGER HELICOPTERS, INC.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	24°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	08:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.499122,-90.690643(est)

Administrative Information

Investigator In Charge (IIC):	Kleckner, Pamela		
Additional Participating Persons:	LARRY BROWN; DES MOINES , IA		
Original Publish Date:	September 28, 1993		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=15483		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.