



Aviation Investigation Final Report

Location: HUASNA, California Accident Number: ANC24LA021

Date & Time: April 6, 2024, 11:33 Local Registration: N8907B

Aircraft: Cessna 172 Aircraft Damage: Substantial

Defining Event: Collision with terr/obj (non-CFIT) **Injuries:** 1 Minor, 1 None

Flight Conducted Under: Part 91: General aviation - Air drop

Analysis

The pilot reported that he was conducting a series of aerial drops for training. After the third pass, he was unable to attain a positive rate of climb. The airplane continued to descend, and the right main landing gear contacted the ground and separated. The airplane veered right and impacted a metal pipe corral fence resulting in substantial damage to the leftwing strut and firewall. The pilot reported no preimpact mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain adequate airspeed during low altitude maneuvers, resulting in a loss of control.

Findings

Personnel issues Aircraft control - Pilot

Aircraft Climb capability - Incorrect use/operation

Aircraft Airspeed - Not attained/maintained

Page 2 of 6 ANC24LA021

Factual Information

History of Flight

Maneuvering-low-alt flying	Aerodynamic stall/spin
Maneuvering-low-alt flying	Collision with terr/obj (non-CFIT) (Defining event)

Pilot Information

Certificate:	Private	Age:	72,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	
Medical Certification:	BasicMed With waivers/limitations	Last FAA Medical Exam:	October 21, 2022
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 9, 2023
Flight Time:	725 hours (Total, all aircraft), 526 hours (Total, this make and model), 632 hours (Pilot In Command, all aircraft)		

Other flight crew Information

Certificate:	Private	Age:	Male
Airplane Rating(s):		Seat Occupied:	Right
Other Aircraft Rating(s):		Restraint Used:	4-point
Instrument Rating(s):		Second Pilot Present:	
Instructor Rating(s):		Toxicology Performed:	
Medical Certification:	Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Page 3 of 6 ANC24LA021

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N8907B
Model/Series:	172	Aircraft Category:	Airplane
Year of Manufacture:	1958	Amateur Built:	
Airworthiness Certificate:	Unknown	Serial Number:	36707
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	October 19, 2023 Annual	Certified Max Gross Wt.:	2200 lbs
Time Since Last Inspection:	13.6 Hrs	Engines:	1
Airframe Total Time:	4465 Hrs at time of accident	Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	On file	Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

meteorological illiorillati			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KSMX,243 ft msl	Distance from Accident Site:	25 Nautical Miles
Observation Time:	11:56 Local	Direction from Accident Site:	61°
Lowest Cloud Condition:	Few / 3500 ft AGL	Visibility	
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/ None	Turbulence Type Forecast/Actual:	Unknown / Unknown
Wind Direction:		Turbulence Severity Forecast/Actual:	Unknown / Unknown
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:			
Departure Point:	San Luis Obispo, CA (KSBP)	Type of Flight Plan Filed:	None
Destination:	HUASNA, CA	Type of Clearance:	None
Departure Time:	11:00 Local	Type of Airspace:	Class G

Page 4 of 6 ANC24LA021

Airport Information

Airport:	Huasna Ranch None	Runway Surface Type:	Dirt;Grass/turf
Airport Elevation:	200 ft msl	Runway Surface Condition:	Dry
Runway Used:	34	IFR Approach:	None
Runway Length/Width:	2400 ft / 50 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	35,-120(est)

Page 5 of 6 ANC24LA021

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:

Original Publish Date: May 3, 2024

Last Revision Date:

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=194055

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC24LA021