













# **Aviation Investigation Notification**

Location: Miami Gardens, FL Accident Number: ERA25LA131

Date & Time:February 25, 2025, 13:16 LocalRegistration:N799RX

Aircraft: MALLORY HORTON AQUA-BEE Injuries: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

The NTSB is conducting a <u>Class 4 investigation</u> into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

### **Aircraft and Owner/Operator Information**

| Aircraft Make: | MALLORY HORTON | Registration:               | N799RX   |
|----------------|----------------|-----------------------------|----------|
| Model/Series:  | AQUA-BEE       | Aircraft Category:          | Airplane |
| Amateur Built: | Yes            |                             |          |
| 0              | On file        | One and in a Contificato(a) | Nama     |

Operator: On file Operating Certificate(s) None Held:

**Operator Designator Code:** 

#### Meteorological Information and Flight Plan

| Conditions at Accident Site:     | VMC                   | Condition of Light:          | Day                       |
|----------------------------------|-----------------------|------------------------------|---------------------------|
| Observation Facility, Elevation: | OPF,4 ft msl          | Observation Time:            | 13:53 Local               |
| Distance from Accident Site:     | 0 Nautical Miles      | Temperature/Dew Point:       | 22°C /17°C                |
| <b>Lowest Cloud Condition:</b>   |                       | Wind Speed/Gusts, Direction: | 13 knots / 24 knots, 140° |
| Lowest Ceiling:                  | Broken / 11000 ft AGL | Visibility:                  | 10 miles                  |
| Altimeter Setting:               | 29.89 inches Hg       | Type of Flight Plan Filed:   |                           |
| Departure Point:                 | Miami Gardens, FL     | Destination:                 | Miami Gardens, FL         |

## **Wreckage and Impact Information**

| Crew Injuries:      | 1 None | Aircraft Damage:     | Substantial         |
|---------------------|--------|----------------------|---------------------|
| Passenger Injuries: |        | Aircraft Fire:       | None                |
| Ground Injuries:    |        | Aircraft Explosion:  | None                |
| Total Injuries:     | 1 None | Latitude, Longitude: | 25.913283,-80.27507 |

## **Administrative Information**

Investigator In Charge (IIC): Mccarter, Lawrence

Additional Participating Persons: Michael H. Torrent; FAA FSDO; Miramar, FL

Investigation Class: Class 4

Note: The NTSB did not travel to the scene of this accident.

Page 2 of 2 ERA25LA131