



Aviation Investigation Final Report

Location: SHERRILL, Arkansas Accident Number: FTW83LA236

Date & Time: May 16, 1983, 08:00 Local **Registration:** N42563

Aircraft: PIPER J3 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 137: Agricultural

Analysis

THE ACFT NOSED OVER ON AN EMERGENCY DOWNWIND LANDING IN A WET RICE FIELD AFTER AN ENG FAILURE. THE PLT STATED THAT THE ENG FAILED AS A RESULT OF WATER IN THE FUEL. THE OPERATOR SERVICES HIS ACFT FROM A PRIVATE UNDERGROUND FUEL STORAGE TANK. AS A RESULT OF RECENT HEAVY RAINS, A LARGE QUANTITY OF WATER HAD ACCUMULATED. ANOTHER ACFT OWNED BY THE OPERATOR WAS CHECKED & WAS FOUND TO CONTAIN A HIGH VOLUME OF WATER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: MANEUVERING - AERIAL APPLICATION

Findings

1. (C) FUEL SUPPLY - IMPROPER - COMPANY/OPERATOR MANAGEMENT

2. (C) FLUID, FUEL - WATER

3. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #3: NOSE OVER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 4. (F) TERRAIN CONDITION - CROP 5. (F) TERRAIN CONDITION - WET

Page 2 of 5 FTW83LA236

Factual Information

Pilot Information

Certificate:	Commercial	Age:	55,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	February 7, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	24000 hours (Total, all aircraft), 21000 hours (Total, this make and model), 24000 hours (Pilot In Command, all aircraft), 335 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N42563
Model/Series:	J3 J3	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	14844
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 12, 1983 Annual	Certified Max Gross Wt.:	1220 lbs
Time Since Last Inspection:	25 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	7715 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	0-360
Registered Owner:	AG AIR INC.	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 FTW83LA236

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	325°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	PINEVILLE , AR (PBF)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Water
Airport Elevation:		Runway Surface Condition:	Rubber deposits
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 4 of 5 FTW83LA236

Administrative Information

Investigator In Charge (IIC):	Daugherty, J.
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=20903

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 FTW83LA236