



Aviation Investigation Final Report

Location: INDIAN SPRINGS, Nevada Accident Number: LAX84FA029

Date & Time: October 23, 1983, 10:15 Local **Registration:** N6912

Aircraft: MOONEY M20F Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation

Analysis

AT 5,500 FT ALTITUDE THE ENG BEGAN SLOWLY LOSING POWER. UNABLE TO MAINTAIN ALTITUDE, THE PLT MADE A GEAR UP LANDING IN ROUGH TERRAIN. EXAMINATION OF THE ENG REVEALED NO DISCREPANIES.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: CRUISE - NORMAL

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: FORCED LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

- Findings
 2. (F) TERRAIN CONDITION ROUGH/UNEVEN
 3. (F) WHEELS UP LANDING PERFORMED PILOT IN COMMAND

Page 2 of 6 LAX84FA029

Factual Information

Pilot Information

Certificate:	Commercial	Age:	31,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 24, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	3500 hours (Total, all aircraft), 9 hours (Total, this make and model), 3400 hours (Pilot In Command, all aircraft), 308 hours (Last 90 days, all aircraft), 80 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 6 LAX84FA029

Aircraft and Owner/Operator Information

Aircraft Make:	MOONEY	Registration:	N6912
Model/Series:	M20F M20F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22-1292
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	September 6, 1983 Unknown	Certified Max Gross Wt.:	2740 lbs
Time Since Last Inspection:	49 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3541 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-360-A1A
Registered Owner:	AIR NEVADA AIRLINES, INC.	Rated Power:	200 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	26°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	DEATH VALLEY , CA (L06)	Type of Flight Plan Filed:	VFR
Destination:	LAS VEGAS , NV (LAS)	Type of Clearance:	None
Departure Time:	09:50 Local	Type of Airspace:	Class G

Page 4 of 6 LAX84FA029

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	36.510242,-115.64096(est)

Page 5 of 6 LAX84FA029

Administrative Information

Investigator In Charge (IIC):	Funk ii, M
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=23897

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX84FA029