



Aviation Investigation Final Report

Location:	BALLICO, California		Accident Number:	LAX85LA113
Date & Time:	January 10, 1985, 15:	30 Local	Registration:	N68444
Aircraft:	FAIRCHILD	M-62C	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 Minor
Flight Conducted Under:	Part 137: Agricultural			

Analysis

AT THE CONCLUSION OF A LOCAL AERIAL APPLICATION FLT, ACFT EXPERIENCED A LOSS OF POWER AND COLLIDED WITH TREES DURING THE SUBSEQUENT FORCED LANDING. EXAMINATON OF THE AIRCRAFT REVEALED A BROKEN FUEL FEED LINE AFT OF THE WOBBLE PUMP AND NO FUEL IN THE LINES OR COMPONENTS FORWARD OF THAT POINT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: CRUISE

Findings 1. (C) FUEL SYSTEM,LINE - FAILURE,TOTAL 2. FLUID,FUEL - STARVATION

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: LANDING - ROLL

Findings

3. (F) TERRAIN CONDITION - NONE SUITABLE 4. (F) OBJECT - TREE(S)

Factual Information

Pilot Information

Certificate:	Commercial	Age:	50,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 9, 1984
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	6080 hours (Total, all aircraft), 270 hours (Total, this make and model), 6011 hours (Pilot In Command, all aircraft), 50 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	FAIRCHILD	Registration:	N68444
Model/Series:	M-62C M-62C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	4593-AE
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	December 21, 1984 Annual	Certified Max Gross Wt.:	2900 lbs
Time Since Last Inspection:	2 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4100 Hrs	Engine Manufacturer:	P&W
ELT:	Not installed	Engine Model/Series:	R-985
Registered Owner:	AG AVIATION, INC.	Rated Power:	450 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MER ,150 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	15:55 Local	Direction from Accident Site:	125°
Lowest Cloud Condition:	Scattered / 5000 ft AGL	Visibility	6 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	1
Wind Direction:	340°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	11°C / 6°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	TURLOCK , CA (015)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:05 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Gravel
Airport Elevation:	159 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	37.469699,-120.649925(est)

Administrative Information

Investigator In Charge (IIC):	Rich, Jeff	
Additional Participating Persons:	LARRY DECOSTA; FRESNO , CA	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=24636	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.