



Aviation Investigation Final Report

Location: PLACERVILLE, California Accident Number: LAX90LA052

Date & Time: December 16, 1989, 11:30 Local Registration: N3266M

Aircraft: PIPER PA-12 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

THE STUDENT PILOT LOST CONTROL OF THE AIRCRAFT DURING A TOUCH AND GO LANDING WHILE BENDING DOWN TO RAISE THE FLAPS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE STUDENT PILOT'S FAILURE TO MAINTAIN DIRECTIONAL CONTROL.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

2. GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Factual Information

Pilot Information

Certificate:	Student	Age:	31,Female
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	June 22, 1989
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	81 hours (Total, all aircraft), 12 hours (Total, this make and model), 6 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N3266M
Model/Series:	PA-12 PA-12	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	12-2150
Landing Gear Type:	Tailwheel	Seats:	3
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed, activated	Engine Model/Series:	0-320
Registered Owner:	UNKNOWN	Rated Power:	150 Horsepower
Operator:	STANCIL AVIATION ENT.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 LAX90LA052

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	14°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:45 Local	Type of Airspace:	

Airport Information

Airport:	PLACERVILLE PVF	Runway Surface Type:	Asphalt
Airport Elevation:	2586 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	None
Runway Length/Width:	4200 ft / 75 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.730369,-120.799148(est)

Page 3 of 4 LAX90LA052

Administrative Information

Investigator In Charge (IIC):	Mucho, R. gary
Additional Participating Persons:	
Original Publish Date:	June 26, 1992
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=26705

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 LAX90LA052