

Aviation Investigation Final Report

Location:	PANAMA CITY, Flo	rida	Accident Number:	MIA86LA130
Date & Time:	April 23, 1986, 07:0)7 Local	Registration:	N90676
Aircraft:	PIPER	PA-60	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 135: Air taxi & commuter - Non-scheduled			

Analysis

THE PLT STATED THAT ON HIS APCH HE HAD A GEAR DOWN & LOCKED INDICATION BUT ON LANDING ROLLOUT, THE NOSE GEAR COMPLETELY COLLAPSED AND THE ACFT SLID TO A STOP ON THE RWY. POST ACCIDENT EXAMINATION OF THE LANDING GEAR SYSTEM REVEALED THAT THE NOSE GEAR COLLAPSED DUE TO A HYDRAULIC LEAK IN THE NOSE GEAR ACTUATOR.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: NOSE GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR, NOSE GEAR - FAILURE, TOTAL

2. (C) HYDRAULIC SYSTEM - LEAK

Factual Information

Pilot Information

Certificate:	Airline transport; Commercial	Age:	33,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	January 8, 1986
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	4074 hours (Total, all aircraft), 749 hours (Total, this make and model), 211 hours (Last 90 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N90676
Model/Series:	PA-60 PA-60	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	60-0331-122
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	January 1, 1986 100 hour	Certified Max Gross Wt.:	5500 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	1800 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-540-K1F5
Registered Owner:	CHEROKEE EXPRESS AIR CARGO INC	Rated Power:	290 Horsepower
Operator:		Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	TLH ,157 ft msl	Distance from Accident Site:	75 Nautical Miles
Observation Time:	07:07 Local	Direction from Accident Site:	260°
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	30°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	TALLAHASSEE , FL (TLH)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	07:30 Local	Type of Airspace:	Class E

Airport Information

Airport:	PANAMA CITY PFN	Runway Surface Type:	Asphalt
Airport Elevation:	20 ft msl	Runway Surface Condition:	Dry
Runway Used:	32	IFR Approach:	None
Runway Length/Width:	6308 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	30.169179,-85.670593(est)

Administrative Information

Investigator In Charge (IIC):	Hill, Bruce
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=31609

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.