



Aviation Investigation Final Report

Location: MARATHON, Florida Accident Number: MIA89LA112

Date & Time: March 21, 1989, 14:30 Local Registration: N39752

Aircraft: WACO UPF-7 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

WHILE LANDING ON RWY 7, THE PLT LOST DIRECTIONAL CONTROL OF THE ACFT. SUBSEQUENTLY, IT GROUND LOOPED TO THE RIGHT & THE LEFT MAIN GEAR COLLAPSED. ABOUT 40 MI WSW AT KEY WEST, FL, THE WIND WAS FROM 140 DEG AT 13 KTS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT FAILED TO MAINTAIN DIRECTIONAL CONTROL OF THE AIRCRAFT AND INADVERTENTLY ALLOWED IT TO GROUND LOOP. CROSSWIND WAS A CONTRIBUTING FACTOR.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - CROSSWIND

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

3. (C) GROUND LOOP/SWERVE - INADVERTENT - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings 4. LANDING GEAR, MAIN GEAR - OVERLOAD

Page 2 of 5 MIA89LA112

Factual Information

Pilot Information

Certificate:	Commercial	Age:	34,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 1, 1988
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	2500 hours (Total, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	WACO	Registration:	N39752
Model/Series:	UPF-7 UPF-7	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	5885
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	W-670-K
Registered Owner:	PEGASUS AIR, INC	Rated Power:	225 Horsepower
Operator:	CONCH CLASSIC AIR TOURS	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	
Operator Does Business As:			

Page 3 of 5 MIA89LA112

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	EYW ,4 ft msl	Distance from Accident Site:	40 Nautical Miles
Observation Time:	14:00 Local	Direction from Accident Site:	266°
Lowest Cloud Condition:	Scattered / 1500 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	13 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	28°C / 20°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:45 Local	Type of Airspace:	Class G

Airport Information

Airport:	MARATHON MTH	Runway Surface Type:	Asphalt
Airport Elevation:	6 ft msl	Runway Surface Condition:	Dry
Runway Used:	7	IFR Approach:	None
Runway Length/Width:	5000 ft / 100 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Page 4 of 5 MIA89LA112

Administrative Information

Investigator In Charge (IIC): Monville, Timothy

Additional Participating
Persons:

Original Publish Date: April 24, 1990

Last Revision Date:
Investigation Class: Class
Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=32412

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MIA89LA112