



# **Aviation Investigation Final Report**

Location: WINTER HAVEN, Florida Accident Number: MIA92LA180

Date & Time: March 1, 1992, 18:05 Local Registration: UNREG

Aircraft: D.W. OWENS STITTS Aircraft Damage: Substantial

**Defining Event:** Injuries: 2 Serious

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

THE PLT PREFLIGHTED THE ACFT, TOOK OFF, FLEW AROUND THE ARPT TRAFFIC PATTERN, LANDED, THEN BOARDED A PAX. THE FLT TOOK OFF AGAIN & THE ENG QUIT WHEN THE FLT WAS APRX 200 FT AGL. THE PLT RESTARTED THE ENG BUT IT WAS NOT PRODUCING POWER. WHILE RETURNING THE ACFT STALLED BUT THE PLT RECOVERED. WHILE ATTEMPTING TO LAND ON THE ARPT PROPERTY, HE PULLED UP TO CLEAR OBSTACLES WHICH WERE AHEAD BUT THE ACFT STALLED AGAIN & IMPACTED THE GROUND. THE DAY AFTER THE ACCIDENT, AN ACFT MECHANIC DRAINED A SMALL QUANTITY OF FUEL FROM THE TANK, WHICH WAS TESTED & FOUND TO BE CONTAMINATED.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FUEL CONTAMINATION AND UNSUITABLE TERRAIN ENCOUNTERED WHILE THE PILOT WAS ATTEMPTING AN EMERGENCY LANDING ON THE AIRPORT PROPERTY.

### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) FLUID, FUEL - CONTAMINATION

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

------

Occurrence #3: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING

#### **Findings**

2. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - ENCOUNTERED - PILOT IN COMMAND

- 3. PULL-UP PERFORMED PILOT IN COMMAND
- 4. STALL/MUSH INADVERTENT PILOT IN COMMAND

Page 2 of 5 MIA92LA180

# **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	50,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Expired	Last FAA Medical Exam:	March 10, 1988
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	10000 hours (Total, all aircraft), 40 hours (Total, this make and model), 8000 hours (Pilot In Command, all aircraft)		

# **Aircraft and Owner/Operator Information**

Aircraft Make:	D.W. OWENS	Registration:	UNREG
Model/Series:	STITTS SA3B STITTS SA3	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	DO-11738
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	November 19, 1990 AAIP	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	15 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	130 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-290-11
Registered Owner:	SEE NARRATIVE	Rated Power:	125 Horsepower
Operator:	DEAL, CARL P.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MIA92LA180

**Meteorological Information and Flight Plan** 

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	LAL ,142 ft msl	Distance from Accident Site:	15 Nautical Miles
Observation Time:	17:53 Local	Direction from Accident Site:	254°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	26°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	(GIF)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	18:00 Local	Type of Airspace:	Class G

# **Airport Information**

Airport:	WINTER HAVEN'S GILBERT GIF	Runway Surface Type:	
Airport Elevation:	146 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing: Fo	rced landing

# **Wreckage and Impact Information**

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:	1 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Serious	Latitude, Longitude:	28.039777,-81.720268(est)

Page 4 of 5 MIA92LA180

#### Administrative Information

Investigator In Charge (IIC): Monville, Timothy **Additional Participating** BEVERLY MORTON; ORLANDO Persons: **SCOTT** STRICKLAND; ORLANDO , FL **Original Publish Date:** August 31, 1993 **Last Revision Date:** Investigation Class: Class Note: **Investigation Docket:** https://data.ntsb.gov/Docket?ProjectID=33134

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MIA92LA180