



Aviation Investigation Final Report

Location: PERKASIE, Pennsylvania Accident Number: NYC84LA211

Date & Time: June 16, 1984, 13:40 Local Registration: N7556

Aircraft: SCHWEIZER SGS 2-33 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE SAILPLANE LOST LIFT AND DURING A FORCED LANDING WIRES WERE SPOTTED ON THE APPROACH. IN ATTEMPTING TO FLY UNDER THE WIRES THE ACFT WAS FLOWN INTO AN EMBANKMENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Findings

1. (C) LACK OF FAMILIARITY WITH AIRCRAFT - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING

Findings

2. TERRAIN CONDITION - NONE SUITABLE

Page 2 of 5 NYC84LA211

Factual Information

Pilot Information

Certificate:	Private	Age:	23,Male
Airplane Rating(s):	None	Seat Occupied:	Front
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	21 hours (Total, all aircraft), 21 hours (Total, this make and model), 12 hours (Pilot In Command, all aircraft), 1 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	SCHWEIZER	Registration:	N7556
Model/Series:	SGS 2-33 SGS 2-33	Aircraft Category:	Glider
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	
Landing Gear Type:	Skid	Seats:	2
Date/Type of Last Inspection:	June 3, 1984 Annual	Certified Max Gross Wt.:	1040 lbs
Time Since Last Inspection:		Engines:	0 Unknown
Airframe Total Time:	1800 Hrs	Engine Manufacturer:	NONE
ELT:	Not installed	Engine Model/Series:	NONE
Registered Owner:	PHILADELPHIA GLIDER	Rated Power:	
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 NYC84LA211

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	27°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	PERKASIE , PA	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	13:40 Local	Type of Airspace:	

Airport Information

Airport:		Runway Surface Type:	Dirt
Airport Elevation:		Runway Surface Condition:	Rough;Vegetation
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Forced landing;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	40.369495,-75.290847(est)

Page 4 of 5 NYC84LA211

Administrative Information

Investigator In Charge (IIC):	Taylor, Vernon
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=35685

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 NYC84LA211