



Aviation Investigation Final Report

Location:	SCHROON LAKE, New York	Accident Number:	NYC88LA103
Date & Time:	March 6, 1988, 11:10 Local	Registration:	N89431
Aircraft:	CESSNA 140	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

DURING LANDING ROLL ON A FROZEN LAKE, THE LEFT LANDING GEAR DUG INTO A SOFT SPOT. THE AIRCRAFT NOSED OVER AND WAS SUBSTANTIALLY DAMAGED. IN HIS RECOMMENDATION FOR PREVENTION OF THIS ACC, THE PLT SAID 'BY NOT LNDG ON ICE.'

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: NOSE OVER
Phase of Operation: LANDING - ROLL

Findings

1. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - SELECTED - PILOT IN COMMAND
2. (F) TERRAIN CONDITION - WEAK ICE

Factual Information

Pilot Information

Certificate:	Private	Age:	24, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	June 10, 1986
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	93 hours (Total, all aircraft), 93 hours (Total, this make and model), 66 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N89431
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	8463
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	April 10, 1987 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1040 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	C-85-12
Registered Owner:	BRET DUNKLEY	Rated Power:	85 Horsepower
Operator:	BRET DUNKLEY	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	2°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	NO. CREEK , NY	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	11:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	43.830757,-73.730552(est)

Administrative Information

Investigator In Charge (IIC): Marcantelli, Vincent

Additional Participating Persons:

Original Publish Date: November 7, 1989

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=36114>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).