



Aviation Investigation Final Report

Location:	ERMA, New Jersey	1	Accident Number:	NYC89LA147
Date & Time:	June 10, 1989, 12:	45 Local	Registration:	N46286
Aircraft:	PIPER	J-3C-65	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 Minor
Flight Conducted Under:	Part 91: General av	viation		

Analysis

THE PILOT WAS UNDER TRAINING FOR A BANNER TOWING LETTER OF AUTHORIZATION AND WAS PRACTICING PICKUPS OF FULL SIZE BANNERS. AFTER PICKUP, AND AT AN ALTITUDE OF 250 FEET, THE AIRPLANE STALLED AND DESCENDED INTO THE TREES. THE PILOT STATED THAT THE PICKUP WAS O.K., BUT THE WINDS WERE GUSTY AND IT WAS A HOT DAY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FAILURE OF THE PILOT TO MAINTAIN AIRSPEED DURING A BANNER PICKUP.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: MANEUVERING

Findings 1. (F) LOW PASS - PERFORMED - PILOT IN COMMAND 2. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND 3. STALL - INADVERTENT - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: MANEUVERING Findings 4. OBJECT - TREE(S)

Factual Information

Pilot Information

Certificate:	Commercial	Age:	35,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	September 14, 1988
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	738 hours (Total, all aircraft), 63 hours (Total, this make and model), 632 hours (Pilot In Command, all aircraft), 80 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N46286
Model/Series:	J-3C-65 J-3C-65	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	G-95
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	1220 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	6491 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	0-235-C
Registered Owner:	PARAMOUNT AIR SERVICE	Rated Power:	100 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	25 knots / 35 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	WILDWOOD , NJ (WWD)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	11:45 Local	Type of Airspace:	Class G

Airport Information

Airport:	Runway Surface Type:	
Airport Elevation:	Runway Surface Condition:	
Runway Used: 0	IFR Approach:	None
Runway Length/Width:	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Hancock, Robert
Additional Participating Persons:	; PHILADELPHIA , PA
Original Publish Date:	September 30, 1991
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=36421

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.