



Aviation Investigation Final Report

Location:	SHEDD, Oregon	Accident Number:	SEA84LA112
Date & Time:	May 7, 1984, 16:00 Local	Registration:	N731SW
Aircraft:	CESSNA 188B	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 137: Agricultural		

Analysis

WHILE LANDING ON A 1600 FT AG STRIP, THE PLT REALIZED HE HAD TOO MUCH SPEED. HOWEVER, THERE WERE POWER LINES AT THE DEPARTURE END OF THE STRIP, SO HE ELECTED NOT TO ATTEMPT A GO-AROUND. HE INTENTIONALLY GROUND LOOPED THE ACFT TO AVOID A DITCH & ROAD AT THE END OF THE STRIP. DURING THE GROUND LOOP, THE RIGHT MAIN GEAR, RIGHT WING & STABILIZER WERE DAMAGED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: OVERRUN
Phase of Operation: LANDING - ROLL

Findings

1. (C) DISTANCE - MISJUDGED - PILOT IN COMMAND
 2. (C) AIRSPEED - MISJUDGED - PILOT IN COMMAND
 3. (F) TERRAIN CONDITION - HIGH OBSTRUCTION(S)
 4. GO-AROUND - NOT PERFORMED - PILOT IN COMMAND
-

Occurrence #2: MAIN GEAR COLLAPSED

Phase of Operation: LANDING

Findings

5. LANDING GEAR,MAIN GEAR - OVERLOAD
6. GROUND LOOP/SWERVE - INTENTIONAL - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Airline transport	Age:	41, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	May 1, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	14800 hours (Total, all aircraft), 2010 hours (Total, this make and model), 14800 hours (Pilot In Command, all aircraft), 150 hours (Last 90 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N731SW
Model/Series:	188B 188B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	188-03128T
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	January 17, 1984 Annual	Certified Max Gross Wt.:	2230 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1540 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Not installed	Engine Model/Series:	IO-520-D
Registered Owner:	AG CARE, INC.	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	30 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	CORVALLIS , OR	Type of Flight Plan Filed:	None
Destination:	SHEDD , OR	Type of Clearance:	None
Departure Time:	15:30 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Grass/turf
Airport Elevation:	250 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	1600 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	44.449344,-123.099182(est)

Administrative Information

Investigator In Charge (IIC): Carrera, Candace

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=39918>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).