



Aviation Investigation Final Report

Location: LAS VEGAS, Nevada Accident Number: SEA84LA205

Date & Time: August 19, 1984, 11:31 Local Registration: N305TA

Aircraft: CESSNA 305A Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

ACCORDING TO WITNESSES THE LEFT WING OF THE ACFT CONTACTED THE GROUND DURING THE LANDING, FOLLOWED BY THE NOSE. ACFT CAME TO REST ON THE NOSE AND LEFT WING AFTER GROUND LOOPING.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: DRAGGED WING, ROTOR, POD, FLOAT OR TAIL/SKID

Phase of Operation: LANDING

Findings

1. (C) FLARE - IMPROPER - PILOT IN COMMAND

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

2. DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Page 2 of 5 SEA84LA205

Factual Information

Pilot Information

Certificate:	Airline transport	Age:	Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:			

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N305TA
Model/Series:	305A 305A	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	22443
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2100 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	0-470-11
Registered Owner:	TIMOTHY G. ALBERT	Rated Power:	190 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 SEA84LA205

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Conditions at Accident Site.	, ,	_	Day
Observation Facility, Elevation:	LAS ,2174 ft msl	Distance from Accident Site:	
Observation Time:	11:49 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 4000 ft AGL	Visibility	50 miles
Lowest Ceiling:	Broken	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	26°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	HENDERSON , NV (NV26)	Type of Flight Plan Filed:	Unknown
Destination:	LAS VEGAS , NV (LAS)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class D

Airport Information

Airport:	MCCARRAN INTERNATIONAL LAS	Runway Surface Type:	Asphalt
Airport Elevation:	2174 ft msl	Runway Surface Condition:	Dry
Runway Used:	19R	IFR Approach:	None
Runway Length/Width:	5000 ft / 75 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	36.119579,-115.079841(est)

Page 4 of 5 SEA84LA205

Administrative Information

Investigator In Charge (IIC): Carrera, Candace

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=39993

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 SEA84LA205