



Aviation Investigation Final Report

Location:	KASAAN PENNINSU, Alaska	Accident Number:	SEA84LA227
Date & Time:	September 12, 1984, 18:30 Local	Registration:	N86922
Aircraft:	BELLANCA 8GCBC	Aircraft Damage:	Substantial
Defining Event:		Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

PLT ATTEMPTED TAKEOFF FROM GLASSY WATER WITH A DEER TIED TO THE LEFT FLOAT. THE RIGHT FLOAT WOULD NOT COME UP ON THE STEP TO ATTAIN LIFT OFF. THE PILOT'S DECISION TO ABORT WAS TOO LATE TO AVOID A COLLISION WITH ROCKS AT THE END OF THE LAKE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: OVERRUN
Phase of Operation: TAKEOFF - ROLL/RUN

- Findings
1. (C) PLANNING/DECISION - IMPROPER - PILOT IN COMMAND
 2. (F) TERRAIN CONDITION - WATER, GLASSY
 3. (C) ABORTED TAKEOFF - DELAYED - PILOT IN COMMAND
-

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER
Phase of Operation: TAKEOFF - ROLL/RUN

Factual Information

Pilot Information

Certificate:	Private	Age:	31, Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	March 9, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	374 hours (Total, all aircraft), 172 hours (Total, this make and model), 328 hours (Pilot In Command, all aircraft), 22 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELLANCA	Registration:	N86922
Model/Series:	8GCBC 8GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	30-74
Landing Gear Type:	Float	Seats:	3
Date/Type of Last Inspection:	June 12, 1984 100 hour	Certified Max Gross Wt.:	1800 lbs
Time Since Last Inspection:	23 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1115 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-360-C2A
Registered Owner:	FRED BASS	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 6000 ft AGL	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	120°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	13°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	KASAAN PENINSUL, AK	Type of Flight Plan Filed:	None
Destination:	KETCHIKAN , AK (KTN)	Type of Clearance:	None
Departure Time:	18:20 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	55.610527,-131.580886(est)

Administrative Information

Investigator In Charge (IIC): Carrera, Candace

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=40010>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).