



Aviation Investigation Final Report

Location:	NR ANCHORAGE, Alaska	Accident Number:	ANC83LA160
Date & Time:	September 3, 1983, 15:20 Local	Registration:	N4773B
Aircraft:	CESSNA 180	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

THE PLT REPORTED THAT THE ACCIDENT OCCURRED WHEN HE WAS LANDING ON A SANDBAR THAT HE HAD PREVIOUSLY USED 3 TIMES, EARLIER THE SAME DAY. REPORTEDLY, HE OVERRAN THE LANDING AREA BY ABOUT 50 FT & ENCOUNTERED AN AREA OF SOFT CLAY & MUD. THE RIGHT WHEEL SANK INTO THE MUD & THE ACFT WENT OVER ON ITS TOP. THE PLT REPORTED THAT THE WIND WAS LIGHT & VARIABLE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: OVERRUN
Phase of Operation: LANDING - ROLL

Findings

1. (C) DISTANCE - MISJUDGED - PILOT IN COMMAND
 2. (C) AIRSPEED - MISJUDGED - PILOT IN COMMAND
-

Occurrence #2: NOSE OVER
Phase of Operation: LANDING - ROLL

Findings

3. (F) TERRAIN CONDITION - SOFT
4. (F) TERRAIN CONDITION - WET

Factual Information

Pilot Information

Certificate:	Commercial	Age:	35, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	October 8, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1885 hours (Total, all aircraft), 204 hours (Total, this make and model), 1800 hours (Pilot In Command, all aircraft), 175 hours (Last 90 days, all aircraft), 100 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N4773B
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	31671
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	August 10, 1983 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:	20 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3625 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, activated	Engine Model/Series:	O-470-J
Registered Owner:	TOM MCGUIRE	Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	25 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	ANCHORAGE , AK (ANC)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	15:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC): Michelangelo, James

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=4163>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).