



Aviation Investigation Final Report

Location: CORDOVA, Alaska Accident Number: ANC87LA048

Date & Time: March 12, 1987, 18:50 Local Registration: N61537

Aircraft: CESSNA 180 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PILOT STATED THAT AFTER TOUCHDOWN AND ABOUT 150 FEET OF THE ROLL, THE PILOT LOST DIRECTIONAL CONTROL CAUSING THE AIRCRAFT TO EXIT THE GRAVEL RUNWAY AND STRIKING TWO PARKED AIRCRAFT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) TERRAIN CONDITION - LOOSE GRAVEL/SANDY

- 2. (C) AIRCRAFT HANDLING IMPROPER PILOT IN COMMAND
- 3. (F) TERRAIN CONDITION SOFT
- 4. (C) DIRECTIONAL CONTROL NOT MAINTAINED PILOT IN COMMAND
- 5. (F) TERRAIN CONDITION WET

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings 6. OBJECT - AIRCRAFT PARKED/STANDING

Page 2 of 6 ANC87LA048

Factual Information

Pilot Information

Certificate:	Commercial	Age:	49,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 15, 1986
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	4320 hours (Total, all aircraft), 426 hours (Total, this make and model), 4215 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 3 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC87LA048

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N61537
Model/Series:	180 180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18052780
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	June 26, 1986 Annual	Certified Max Gross Wt.:	3190 lbs
Time Since Last Inspection:	73 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2648 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	0-470-4
Registered Owner:	NORMAN R. ROBERTS	Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	5°C / 2°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ition	
Departure Point:	ANCHORAGE , AK (MRI)	Type of Flight Plan Filed:	VFR
Destination:		Type of Clearance:	None
Departure Time:	17:45 Local	Type of Airspace:	Class G

Page 4 of 6 ANC87LA048

Airport Information

Airport:	CORDOVA CKU	Runway Surface Type:	Gravel
Airport Elevation:	12 ft msl	Runway Surface Condition:	Wet
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	1900 ft / 80 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	60.789337,-145.610717(est)

Page 5 of 6 ANC87LA048

Administrative Information

Investigator In Charge (IIC): Kobelnyk, George

Additional Participating
Persons:

Original Publish Date: March 30, 1988

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=4831

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC87LA048