

Aviation Investigation Final Report

Location:	HAWKINSVILLE, Geo	orgia	Accident Number:	ATL82DA277
Date & Time:	September 16, 1982,	, 18:00 Local	Registration:	N2103V
Aircraft:	CESSNA	120	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General avia	tion - Personal		

Analysis

THE AIRCRAFT NOSED OVER WHILE LANDING IN A PEANUT FIELD. THE PILOT REPORTED THAT THE TERRAIN WAS SOFTER THAN HE REALIZED, AND WHEN HE APPLIED BRAKE PRESSURE, THE PLANE NOSED OVER. HE BELIEVED THE ACCIDENT WOULD NOT HAVE OCCURRED IT BRAKES HAD NOT BEEN APPLIED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: NOSE OVER Phase of Operation: LANDING - ROLL

Findings

1. (F) TERRAIN CONDITION - SOFT

2. (C) BRAKES(NORMAL) - IMPROPER USE OF - PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	29,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 5, 1981
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	152 hours (Total, all aircraft), 87 hours (Pilot In Command, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N2103V
Model/Series:	120 120	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	14728
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4453 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Not installed	Engine Model/Series:	0-200A
Registered Owner:	LOCK WOOD WHIGAM, III	Rated Power:	
Operator:	LOCK WOOD WHIGAM, III	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	80°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	HAWKINSVILLE , GA	Type of Flight Plan Filed:	None
Destination:	HAWKINSVILLE , GA	Type of Clearance:	None
Departure Time:	17:00 Local	Type of Airspace:	

Airport Information

Airport:		Runway Surface Type:	Dirt;Grass/turf
Airport Elevation:	0 ft msl	Runway Surface Condition:	Soft
Runway Used:	9	IFR Approach:	None
Runway Length/Width:	3000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	September 16, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=70982

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.