



Aviation Investigation Final Report

Location:	LANCASTER, Ohio	Accident Number:	CHI82DA142
Date & Time:	April 27, 1982, 19:10 Local	Registration:	N6739B
Aircraft:	PIPER PA-22-150	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

THE PILOT WAS PRACTICING TAKEOFFS AND LANDINGS ON RUNWAY 10. ON THE SECOND LANDING THE AIRCRAFT BOUNCED AND DRIFTED. THE AIRCRAFT TOUCHED DOWN ON THE RUNWAY A SECOND TIME COLLAPSING THE NOSE GEAR. THE WIND WAS REPORTED AS 010 DEGREES AT 13 KTS. GUSTS TO 15 KTS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) LEVEL OFF - IMPROPER - PILOT IN COMMAND
2. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND
3. (F) WEATHER CONDITION - GUSTS

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Occurrence #3: NOSE GEAR COLLAPSED
Phase of Operation: LANDING - ROLL

Findings

4. (F) LANDING GEAR, NOSE GEAR - OVERLOAD

Factual Information

Pilot Information

Certificate:	Private	Age:	56, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	November 4, 1980
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	128 hours (Total, all aircraft), 100 hours (Total, this make and model), 93 hours (Pilot In Command, all aircraft), 28 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N6739B
Model/Series:	PA-22-150 PA-22-150	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	22-4072
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1950 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3675 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	O-320-A1A
Registered Owner:	C. M. SERVICES INC.	Rated Power:	150 Horsepower
Operator:	C. M. SERVICES INC.	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dusk
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	10 miles
Lowest Ceiling:	Overcast / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	13 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	50°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	LANCASTER , OH (I15)	Type of Flight Plan Filed:	None
Destination:	LANCASTER , OH (I15)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	

Airport Information

Airport:	FAIRFIELD COUNTY I15	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	10	IFR Approach:	
Runway Length/Width:	5000 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.719409,-82.589607(est)

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:

Original Publish Date: April 27, 1983

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=71348>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).