



Aviation Investigation Final Report

Location:	SANTA FE, New Mexico	Accident Number:	FTW82DA329
Date & Time:	August 15, 1982, 09:15 Local	Registration:	N67834
Aircraft:	CESSNA 152	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

Analysis

THE STUDENT PILOT WAS ON HIS FIRST SUPERVISED SOLO FLIGHT. DURING A TOUCH-AND-GO LANDING, WHEN POWER WAS ADDED FOR TAKEOFF, AT ABOUT 50 KTS, HE LOST CONTROL OF THE AIRCRAFT DEPARTED THE RUNWAY, IT STRUCK A BUSH AND NOSED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER
Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. TOUCH-AND-GO - INITIATED - PILOT IN COMMAND
 2. LACK OF TOTAL EXPERIENCE - PILOT IN COMMAND
 3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND
 4. (C) GROUND LOOP/SWERVE - NOT MAINTAINED - PILOT IN COMMAND
-

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER
Phase of Operation: TAKEOFF - ROLL/RUN

Findings

5. (F) TERRAIN CONDITION - HIGH VEGETATION

Factual Information

Pilot Information

Certificate:	Student	Age:	26, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	August 9, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	8 hours (Total, all aircraft), 8 hours (Total, this make and model), 8 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N67834
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	15282045
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1750 lbs
Time Since Last Inspection:	66 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1238 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	O-235-L2C
Registered Owner:	SANTA FE AVIATION	Rated Power:	110 Horsepower
Operator:	SANTA FE AVIATION	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:	09:15 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	40 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	9 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	73°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	SANTA FE , NM (SAF)	Type of Flight Plan Filed:	None
Destination:	SANTA FE , NM (SAF)	Type of Clearance:	None
Departure Time:	09:15 Local	Type of Airspace:	

Airport Information

Airport:	SANTA FE MUNICIPAL SAF	Runway Surface Type:	Macadam
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	2	IFR Approach:	
Runway Length/Width:	8322 ft / 100 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	35.740634,-105.8609(est)

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:

Original Publish Date: August 15, 1983

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=72535>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).