

Aviation Investigation Final Report

Location:	TUCSON, Arizona		Accident Number:	LAX82FUJ33
Date & Time:	March 10, 1982, 13	:25 Local	Registration:	N8492B
Aircraft:	HATZ	CB-1	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General av	iation - Personal		

Analysis

THE PILOT REPORTED THAT DURING LANDING, HE FLARED EARLY, MISJUDGED HIS HEIGHT, AND LANDED HARD. THE LEFT GEAR FAILED DURING TOUCHDOWN, AND THE AIRCRAFT FLIPPED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings
1. (C) FLARE - IMPROPER - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 2. (F) LANDING GEAR, MAIN GEAR - OVERLOAD Occurrence #3: NOSE OVER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Factual Information

Pilot Information

T not information			
Certificate:	Private	Age:	58,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 3, 1980
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	278 hours (Total, all aircraft), 20 hours (Total, this make and model), 219 hours (Pilot In Command, all aircraft), 8 hours (Last 90 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	HATZ	Registration:	N8492B
Model/Series:	CB-1 CB-1	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:		Serial Number:	10124C
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1250 lbs
Time Since Last Inspection:	20 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	20 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	0-290
Registered Owner:	R A CHANEY JR	Rated Power:	160 Horsepower
Operator:	R A CHANEY JR	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dav
	violati (vivio)	-	buy
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	50 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	360°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	80°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	TUCSON , AZ	Type of Flight Plan Filed:	None
Destination:	TUCSON , AZ	Type of Clearance:	None
Departure Time:	12:55 Local	Type of Airspace:	

Airport Information

Airport:	RYAN FIELD	Runway Surface Type:	Dirt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	34	IFR Approach:	
Runway Length/Width:	3500 ft / 0 ft	VFR Approach/Landing:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	March 10, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=72868

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.