

Aviation Investigation Final Report

Location:	YUMA, Colorado		Accident Number:	DEN82DA165
Date & Time:	August 16, 1982, 16:00	0 Local	Registration:	N5138X
Aircraft:	BELLANCA	7GCBC	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal			

Analysis

THE PILOT STATED THAT AS HE TOUCHED DOWN THE AIRCRAFT PORPOISED "A COUPLE OF TIMES." WHEN THE AIRCRAFT HAD SLOWED TO APPROXIMATELY 25-30 MPH IT RAN OFF THE RUNWAY INTO SOFT DIRT AND NOSED OVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings

- 1. (F) WEATHER CONDITION GUSTS
- 2. (C) RECOVERY FROM BOUNCED LANDING DELAYED PILOT IN COMMAND
- 3. (C) GROUND LOOP/SWERVE UNCONTROLLED PILOT IN COMMAND

Factual Information

Pilot Information

Certificate:	Private	Age:	34,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 5, 1982
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	137 hours (Total, all aircraft), 30 hours (Total, this make and model), 46 hours (Pilot In Command, all aircraft), 5 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELLANCA	Registration:	N5138X
Model/Series:	7GCBC 7GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	159
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1570 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	0-320-A-2B
Registered Owner:	FREDERICK L. HILL	Rated Power:	150 Horsepower
Operator:	FREDERICK L. HILL	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	Unknown	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	135°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	85°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	7NM EAST OF YUM, CO	Type of Flight Plan Filed:	None
Destination:	7NM EAST OF YUM, CO	Type of Clearance:	None
Departure Time:	15:50 Local	Type of Airspace:	

Airport Information

Airport:	YUMA MUNICIPAL 2V6	Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	
Runway Length/Width:	4100 ft / 50 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	40.119266,-102.720085(est)

Administrative Information

Investigator In Charge (IIC):	
Additional Participating Persons:	
Original Publish Date:	August 16, 1983
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=73115

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.