



Aviation Investigation Final Report

Location: Nikiski, Alaska Accident Number: ANC12CA104

Date & Time: September 8, 2012, 20:15 Local Registration: N9723K

Aircraft: Stinson 108-2 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 4 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot was landing his tailwheel-equipped airplane on a tidal beach. During the landing roll, the right main landing gear contacted soft sand, which pulled the nose of the airplane to the right. The airplane continued to the right and hit a bluff, sustaining substantial damage to the fuselage. The pilot indicated that there were no preaccident mechanical anomalies with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's selection of an unsuitable landing surface, which resulted in a loss of control during the landing roll.

Findings

Personnel issues Decision making/judgment - Pilot

Environmental issues Soft surface - Contributed to outcome

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event)
Landing-landing roll	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Private	Age:	40,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 1, 2010
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 13, 2011
Flight Time:	482 hours (Total, all aircraft), 250 ho aircraft)	ours (Total, this make and model), 3 ho	ours (Last 24 hours, all

Aircraft and Owner/Operator Information

Aircraft Make:	Stinson	Registration:	N9723K
Model/Series:	108-2	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	108-2723
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	August 1, 2012 Annual	Certified Max Gross Wt.:	
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	FRANKLIN
ELT:	C91A installed, not activated	Engine Model/Series:	6A4150 SERIES
Registered Owner:	On file	Rated Power:	150 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 2 of 4 ANC12CA104

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAEN	Distance from Accident Site:	10 Nautical Miles
Observation Time:	17:53 Local	Direction from Accident Site:	180°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	260°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29.75 inches Hg	Temperature/Dew Point:	10°C / 4°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Homer, AK (PAHO)	Type of Flight Plan Filed:	Unknown
Destination:	Nikiski, AK	Type of Clearance:	None
Departure Time:	19:30 Local	Type of Airspace:	

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	60.9225,-150.733612(est)

Page 3 of 4 ANC12CA104

Administrative Information

Investigator In Charge (IIC):	Shaver, Christopher
Additional Participating Persons:	Charles Strange; FAA Anchorage FSDO; Anchorage, AK
Original Publish Date:	December 19, 2012
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=85027

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 ANC12CA104