



Aviation Investigation Final Report

Location:	Winter Haven, Florida	Accident Number:	GAA16CA053
Date & Time:	November 13, 2015, 10:30 Local	Registration:	N688KA
Aircraft:	SWEENEY TIMOTHY J RANS S6-ES	Aircraft Damage:	Substantial
Defining Event:	Abnormal runway contact	Injuries:	1 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot reported that during an intentional landing on the grass parallel to an asphalt runway, he touched down fast and bounced "slightly." He then became distracted when another pilot reported over the radio that a coyote was crossing the runway. Subsequently, he "let the nose wheel down too early and too quickly." The nose gear collapsed and the airplane nosed over. The vertical stabilizer was substantially damaged.

The pilot reported that there were no mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's improper landing flare, which resulted in a nose gear collapse and nose over.

Findings

Aircraft

Personnel issues

Aircraft control - Pilot Landing flare - Incorrect use/operation

Factual Information

History of Flight

Landing-flare/touchdown	Abnormal runway contact (Defining event)	
Landing-landing roll	Nose over/nose down	
Landing-landing roll	Collision with terr/obj (non-CFIT)	

Pilot Information

Certificate:	Private	Age:	62,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Sport pilot None	Last FAA Medical Exam:	
Occupational Pilot:	No	Last Flight Review or Equivalent:	June 6, 2015
Flight Time:	1662 hours (Total, all aircraft), 765 hours (Total, this make and model), 1473 hours (Pilot In Command, all aircraft), 34 hours (Last 90 days, all aircraft), 19 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	SWEENEY TIMOTHY J	Registration:	N688KA
Model/Series:	RANS S6-ES	Aircraft Category:	Airplane
Year of Manufacture:	2009	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special); Special flight (Special)	Serial Number:	05081884-ES
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	July 10, 2015 Annual	Certified Max Gross Wt.:	1320 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	875.1 Hrs as of last inspection	Engine Manufacturer:	Rotax
ELT:	C91A installed, not activated	Engine Model/Series:	912UL
Registered Owner:	On file	Rated Power:	80 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KGIF,145 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	15:53 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Overcast / 7000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	350°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.07 inches Hg	Temperature/Dew Point:	24°C / 21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	ORLANDO, FL (ISM)	Type of Flight Plan Filed:	None
Destination:	Winter Haven, FL (GIF)	Type of Clearance:	None
Departure Time:	10:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	WINTER HAVEN'S GILBERT GIF	Runway Surface Type:	Grass/turf
Airport Elevation:	145 ft msl	Runway Surface Condition:	Dry
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	28.062778,-81.751945(est)

Administrative Information

Investigator In Charge (IIC):	Gerhardt, Adam
Additional Participating Persons:	Theodore Rodriguez; Orlando FSDO (FAA); Orlando, FL
Original Publish Date:	January 15, 2016
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=92339

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.