



Aviation Investigation Final Report

Location: Winnemucca, Nevada Accident Number: GAA17CA054

Date & Time: October 25, 2016, 09:00 Local Registration: N7711L

Aircraft: Cessna A185 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of a tailwheel-equipped airplane reported that during the landing roll, the airplane veered to the right and he applied left rudder to stop the veer. Subsequently, the airplane continued to the right, ground looped, and the left wing impacted the runway.

The left aileron sustained substantial damage.

The pilot reported no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing roll.

Findings

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event)	
Landing-landing roll	Collision with terr/obj (non-CFIT)	

Pilot Information

Certificate:	Private	Age:	83,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	September 29, 2014
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 2248 hours (Total, all aircraft), 2100 hours (Total, this make and model), 2248 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 0.5 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N7711L
Model/Series:	A185 E	Aircraft Category:	Airplane
Year of Manufacture:	1969	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	185-1521
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	January 6, 2016 Annual	Certified Max Gross Wt.:	3200 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3485 Hrs as of last inspection	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-520-D
Registered Owner:	On file	Rated Power:	300 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 2 of 4 GAA17CA054

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KWMC,4307 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	15:56 Local	Direction from Accident Site:	0°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/ None
Wind Direction:		Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.09 inches Hg	Temperature/Dew Point:	11°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	WINNEMUCCA, NV (WMC)	Type of Flight Plan Filed:	None
Destination:	WINNEMUCCA, NV (WMC)	Type of Clearance:	None
Departure Time:	08:30 Local	Type of Airspace:	Class G

Airport Information

Airport:	WINNEMUCCA MUNI WMC	Runway Surface Type:	Asphalt
Airport Elevation:	4307 ft msl	Runway Surface Condition:	Dry
Runway Used:	02	IFR Approach:	None
Runway Length/Width:	4800 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	40.896667,-117.805831(est)

Page 3 of 4 GAA17CA054

Administrative Information

Investigator In Charge (IIC):	Corporate Adopa
Investigator In Charge (IIC):	Gerhardt, Adam
Additional Participating Persons:	Mark D Hinzman; FAA; Reno, NV
Original Publish Date:	January 18, 2017
Last Revision Date:	
Investigation Class:	Class
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=94329

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 GAA17CA054