



Aviation Investigation Notification

Location:	Washington, WI	Accident Number:	CEN21LA021
Date & Time:	October 18, 2020, 14:00 Local	Registration:	N31136
Aircraft:	Robinson Helicopter Company R44 II	Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	Robinson Helicopter Company	Registration:	N31136
Model/Series:	R44 II	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	On file	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	2P2,652 ft msl	Observation Time:	13:55 Local
Distance from Accident Site:	0 Nautical Miles	Temperature/Dew Point:	5.6°C /-2.2°C
Lowest Cloud Condition:	Scattered / 3800 ft AGL	Wind Speed/Gusts, Direction:	9 knots / 14 knots, 290°
Lowest Ceiling:		Visibility:	10 miles
Altimeter Setting:	30.07 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Washington, WI	Destination:	Ephraim, WI (3D2)

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	45.389097,-86.924557 (est)

Administrative Information

Investigator In Charge (IIC):	Hodges, Michael
Additional Participating Persons:	Todd Davis; FAA Milwaukee FSDO; Milwaukee, WI
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.