



Aviation Investigation Notification

Location:	Pahrump, NV	Accident Number:	WPR21LA021
Date & Time:	October 16, 2020, 10:00 Local	Registration:	N500DL
Aircraft:	Robinson R44	Injuries:	2 Minor, 1 None
Flight Conducted Under:	Part 91: General aviation - Business		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	Robinson	Registration:	N500DL
Model/Series:	R44	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	Spring Mountain Raceway LLC	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KDRA,3230 ft msl	Observation Time:	09:53 Local
Distance from Accident Site:	28 Nautical Miles	Temperature/Dew Point:	22°C /-10°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	15 knots / , 30°
Lowest Ceiling:		Visibility:	10 miles
Altimeter Setting:	30.25 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Pahrump, NV	Destination:	Pahrump, NV

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 Minor	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 Minor, 1 None	Latitude, Longitude:	36.165812,-115.90381

Administrative Information

Investigator In Charge (IIC):	Hicks, Michael
Additional Participating Persons:	Carey Atnip; FAA; Las Vegas, NV
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.