



Aviation Investigation Notification

Location:	Morris, IL	Accident Number:	CEN21LA095
Date & Time:	December 20, 2020, 16:45 Local	Registration:	N3264U
Aircraft:	ROBINSON HELICOPTER R44	Injuries:	1 Minor
Flight Conducted Under:	Part 91: General aviation - Personal		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER	Registration:	N3264U
Model/Series:	R44	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	On file	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	C09,584 ft msl	Observation Time:	16:35 Local
Distance from Accident Site:	0 Nautical Miles	Temperature/Dew Point:	3°C /0°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	6 knots / , 250°
Lowest Ceiling:		Visibility:	10 miles
Altimeter Setting:	29.8 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Morris, IL	Destination:	Morris, IL

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	41.428698,-88.420823

Administrative Information

Investigator In Charge (IIC):	Lindberg, Joshua
Additional Participating Persons:	Kristian Kortokrax; Federal Aviation Administration; Des Plaines, IL
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.