

VIEW OF WING

- No Soot on inside
- No Pumps ? No ~~Doors~~ Access Panels
- Lower Surface has soot Except under Nacelle fairing

LW14
C2017 (Green)
Left lower Wing Skin around Boost Pump Access doors

Jim Powers

Roy Hutts — BOEING
— MEA
— FAM
— TWA
— NTSB