

Systems 9 - Exhibit No. 9B - Photo 9. Figure 9b. Corrosion products on glass to metal seal of N.O.