

Systems 9 - Photo 44. Airplane 19. B-767 thrust reverser indication printed circuit card with burned track. Burned track was connected to the burned wire bundle through other wiring.