Carburetor Icing Probability Chart



ERA23LA127:
Temperature: 73.4° F
Dew Point: 57.2° F