



Aviation Investigation Notification

Location:	West Palm Beach, FL	Accident Number:	ERA21LA117
Date & Time:	January 26, 2021, 17:15 Local	Registration:	N474AT
Aircraft:	Robinson R22	Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation - Instructional		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	Robinson	Registration:	N474AT
Model/Series:	R22 Beta	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	Palm Beach Helicopters	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	LNA,14 ft msl	Observation Time:	17:15 Local
Distance from Accident Site:	0 Nautical Miles	Temperature/Dew Point:	26°C /20°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	10 knots / None, 150°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	30.01 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	West Palm Beach, FL	Destination:	West Palm Beach, FL

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	26.593056,-80.085065 (est)

Administrative Information

Investigator In Charge (IIC):	Kemner, Heidi
Additional Participating Persons:	Julie-Ann Nydegger; FAA -IFO; Miramar, FL David Gerlach; FAA - AVP100; Washington, DC
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.