





Injuries:



1 Fatal





Aviation Investigation Preliminary Report

Location: Kodiak, AK **Accident Number:** ANC21LA020

Date & Time: N1767 March 2, 2021, 15:39 Local Registration:

ROBINSON HELICOPTER CO R66

Flight Conducted Under: Part 91: General aviation - Personal

Aircraft and Owner/Operator Information

Aircraft Make: **ROBINSON HELICOPTER** Registration: N1767

CO

Model/Series: **R66 Aircraft Category:** Helicopter

Amateur Built:

Aircraft:

Operator: On file **Operating Certificate(s)** On-demand air taxi (135)

Held:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	Unknown	Condition of Light:	Day
Observation Facility, Elevation:	PASO,29 ft msl	Observation Time:	15:23 Local
Distance from Accident Site:	32 Nautical Miles	Temperature/Dew Point:	-3°C /-5°C
Lowest Cloud Condition:		Wind Speed/Gusts, Direction:	4 knots / None
Lowest Ceiling:	Overcast / 1000 ft AGL	Visibility:	10 miles
Altimeter Setting:	29.16 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:	Anchorage, AK (MRI)	Destination:	Kodiak, AK (ADQ)

Wreckage and Impact Information

Crew Injuries:	1 Fatal	Aircraft Damage:	Destroyed
Passenger Injuries:	N/A	Aircraft Fire:	Unknown
Ground Injuries:	N/A	Aircraft Explosion:	Unknown
Total Injuries:	1 Fatal	Latitude, Longitude:	58.872527,-152.13761 (est)

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	David Longan; FAA; Juneau, AK Thom Webster; Robinson Helicopter Company; Torrance, CA
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.

Page 2 of 2 ANC21LA020