



# Aviation Investigation Preliminary Report

<b>Location:</b>	Johnson, KS	<b>Accident Number:</b>	CEN21LA184
<b>Date &amp; Time:</b>	April 5, 2021, 17:00 Local	<b>Registration:</b>	N8348X
<b>Aircraft:</b>	ROBINSON HELICOPTER R44	<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	ROBINSON HELICOPTER	<b>Registration:</b>	N8348X
<b>Model/Series:</b>	R44	<b>Aircraft Category:</b>	Helicopter
<b>Amateur Built:</b>			
<b>Operator:</b>	SEGER ROBERT E	<b>Operating Certificate(s) Held:</b>	None
<b>Operator Designator Code:</b>			

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	VMC	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KSPD,4383 ft msl	<b>Observation Time:</b>	16:56 Local
<b>Distance from Accident Site:</b>	38 Nautical Miles	<b>Temperature/Dew Point:</b>	29°C /-7°C
<b>Lowest Cloud Condition:</b>	Clear	<b>Wind Speed/Gusts, Direction:</b>	9 knots / None, 170°
<b>Lowest Ceiling:</b>			
<b>Altimeter Setting:</b>	29.64 inches Hg	<b>Type of Flight Plan Filed:</b>	NONE
<b>Departure Point:</b>	Johnson, KS	<b>Destination:</b>	Johnson, KS

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	37.667167,-101.988 (est)

## Administrative Information

---

<b>Investigator In Charge (IIC):</b>	Lindberg, Joshua
<b>Additional Participating Persons:</b>	Michael LeBlanc; Federal Aviation Administration; Wichita, KS
<b>Investigation Class:</b>	<a href="#">Class 3</a>
<b>Note:</b>	The NTSB did not travel to the scene of this accident.