













# **Aviation Investigation Notification**

Location: Palm Gardens, NV **Accident Number:** WPR21LA185

Date & Time: May 6, 2021, 13:30 Local Registration: N972BW

MCDONNELL DOUGLAS HELI CO Aircraft: Injuries: 2 None 369FF

Flight Conducted Under: Part 133: Rotorcraft ext. load

The NTSB is conducting a <u>Class 4 investigation</u> into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

#### Aircraft and Owner/Operator Information

Aircraft Make: MCDONNELL DOUGLAS Registration: N972BW

**HELI CO** 

Model/Series: 369FF Aircraft Category: Helicopter

**Amateur Built:** 

**Operating Certificate(s)** Rotorcraft external load Operator: Summit Helicopter Inc.

(133), On-demand air taxi Held:

(135)

**Operator Designator Code:** M55L

### Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KIFP,695 ft msl	Observation Time:	13:48 Local
Distance from Accident Site:	17 Nautical Miles	Temperature/Dew Point:	38°C /-4°C
<b>Lowest Cloud Condition:</b>	Few / 16000 ft AGL	Wind Speed/Gusts, Direction:	11 knots / , 170°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	29.86 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	Palm Gardens, NV	Destination:	Palm Gardens, NV

## **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	35.196949,-114.85647 (est)

## **Administrative Information**

Investigator In Charge (IIC): Nixon, Albert

**Additional Participating Persons:** 

Investigation Class: Class 4

**Note:** The NTSB did not travel to the scene of this accident.

Page 2 of 2 WPR21LA185