

Aviation Investigation Preliminary Report

Location:	Rome, NY	Accident Number:	ERA21LA275
Date & Time:	June 29, 2021, 13:47 Local	Registration :	N134VG
Aircraft:	Bell 206	Injuries:	3 Minor
Flight Conducted Under:	Part 91: General aviation - Instructional		

Aircraft and Owner/Operator Information

Aircraft Make:	Bell	Registration:	N134VG	
Model/Series:	206 в	Aircraft Category:	Helicopter	
Amateur Built:				
Operator:	Aviation Services Unlimited LLC	Operating Certificate(s) Held:	Commuter air carrier (135)	
Operator Designator Code:	R73A			
Meteorological Information and Flight Plan				
Conditions at Accident Site:	VMC	Condition of Light:	Day	
Observation Facility, Elevation:	RME,505 ft msl	Observation Time:	13:49 Local	
Observation Facility, Elevation: Distance from Accident Site:	RME,505 ft msl 1 Nautical Miles	Observation Time: Temperature/Dew Point:	13:49 Local 32°C /22°C	
•			32°C /22°C	
Distance from Accident Site:	1 Nautical Miles	Temperature/Dew Point:	32°C /22°C	
Distance from Accident Site: Lowest Cloud Condition:	1 Nautical Miles Clear	Temperature/Dew Point: Wind Speed/Gusts, Direction	32°C /22°C : 9 knots / None, 260°	
Distance from Accident Site: Lowest Cloud Condition: Lowest Ceiling:	1 Nautical Miles Clear None	Temperature/Dew Point: Wind Speed/Gusts, Direction Visibility:	32°C /22°C : 9 knots / None, 260° 10 miles	

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	2 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 Minor	Latitude, Longitude:	43.225037,-75.394489 (est)

Administrative Information

Investigator In Charge (IIC):	Brazy, Douglass
Additional Participating Persons:	Timothy Shaver; FAA/FSDO; Albany, NY Jack Johnson; Rolls-Royce Corporation; Indianapolis, IN Mark Stuntzner; Bell Flight Safety; Fort Worth, TX Nora Vallée; Transportation Safety Board of Canada; Gatineau, Québec, OF
Investigation Class:	Class 3
Note:	The NTSB did not travel to the scene of this accident.