



Aviation Investigation Notification

Location:	West Liberty, IA	Accident Number:	CEN21LA339
Date & Time:	July 20, 2021, 17:20 Local	Registration:	N983HA
Aircraft:	ROBINSON HELICOPTER COMPANY R44 II	Injuries:	1 Minor
Flight Conducted Under:	Part 137: Agricultural		

The NTSB is conducting a [Class 4 investigation](#) into this event. A preliminary report will not be issued but a final report will be released at the conclusion of the investigation.

Aircraft and Owner/Operator Information

Aircraft Make:	ROBINSON HELICOPTER COMPANY	Registration:	N983HA
Model/Series:	R44 II	Aircraft Category:	Helicopter
Amateur Built:			
Operator:	On file	Operating Certificate(s) Held:	None
Operator Designator Code:			

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KMUT, 547 ft msl	Observation Time:	17:15 Local
Distance from Accident Site:	13 Nautical Miles	Temperature/Dew Point:	30°C / 21°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	5 knots / None, 300°
Lowest Ceiling:	None	Visibility:	10 miles
Altimeter Setting:	30.06 inches Hg	Type of Flight Plan Filed:	NONE
Departure Point:		Destination:	

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	N/A	Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	41.57,-91.2638 (est)

Administrative Information

Investigator In Charge (IIC):	Link, Samantha
Additional Participating Persons:	Michael Newhall; Federal Aviation Administration; Des Moines, IA
Investigation Class:	Class 4
Note:	The NTSB did not travel to the scene of this accident.