











Aviation Investigation Preliminary Report

Location: Arnaudville, LA **Accident Number: CEN21LA389**

Date & Time: August 27, 2021, 08:00 Local Registration: N827SH

ROBINSON HELICOPTER R22 Aircraft: Injuries: 1 Minor **BETA**

Flight Conducted Under: Part 91: General aviation - Positioning

Aircraft and Owner/Operator Information

Aircraft Make: Registration: N827SH **ROBINSON HELICOPTER**

Model/Series: R22 BETA **Aircraft Category:** Helicopter

Amateur Built:

Operator: 1 ACADIANA HELICOPTERS **Operating Certificate(s)** Agricultural aircraft (137)

> **COMPANY LLC** Held:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site:	VMC	Condition of Light:	Day
Observation Facility, Elevation:	KLFT,42 ft msl	Observation Time:	06:53 Local
Distance from Accident Site:	12 Nautical Miles	Temperature/Dew Point:	23°C /22°C
Lowest Cloud Condition:	Clear	Wind Speed/Gusts, Direction:	3 knots / , 40°
Lowest Ceiling:	None	Visibility:	7 miles
Altimeter Setting:	29.96 inches Hg	Type of Flight Plan Filed:	None
Departure Point:	New Iberia, LA	Destination:	Arnaudville, LA

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:		Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	30.395296,-91.934586 (est)

Administrative Information

Investigator In Charge (IIC): Sauer, Aaron

Additional Participating Persons: Paul Marks; FAA; Baton Rouge, LA

Investigation Class: Class 3

Note: The NTSB did not travel to the scene of this accident.

Page 2 of 2 CEN21LA389